



ASM-021

SERVICE BULLETIN ASM-021

Product: Antenna Systems Monitor

Subject: Firmware 2.82 Release

Date: 3rd July 2017

Description

This Service Bulletin announces the release of baseline 2.82 firmware for the Antenna System Monitor (ASM) series products.

The version 2.82 firmware update file ("FFP") is available for download from the RFI website http://www.rfiwireless.com.au/multicoupling-monitoring/monitoring/antenna-system-monitor-asm3852.html#tab_downloads, and may be flashed into existing ASM models by following the *Maintenance – Firmware Update* process in the Graphical User Interface (GUI) or User Manual.

Product Enhancement

This version 2.82 firmware supports the use of an updated flash memory device that is now used in the manufacture of the ASM products. No new ASM features are introduced in this firmware release. Some ASM units using the updated memory chip may have been supplied with earlier versions of firmware installed and could subsequently experience difficulties in being upgraded to later firmware versions. If upgrading recently purchased ASM units exhibit difficulties during a firmware upgrade, please contact RFI for assistance. This version 2.82 is fully compatible with ASM units built using the older flash memory device.

Upgrading to Firmware 2.82

Note: Please read all Service Bulletins published from the release of the firmware currently operating in your ASM prior to commencing an upgrade to this version 2.82 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your ASM.

The required intermediate firmware version transitions are;

- Firmware below version 2.0 must transition through version 2.0 or 2.05 prior to attempting an update to 2.1 or above.
- Firmware below 2.60 must transition through version 2.60 prior to attempting an update to 2.70 or above.

Cost Impact

Firmware version 2.82 is available to RFI customers at no charge.

- END -