



ASM-013

SERVICE BULLETIN ASM-013

Product: Antenna System Monitor

Subject: Firmware 2.50c Release

Date: 17th September 2014

Description

This Service Bulletin announces the release of baseline 2.50c firmware for the Antenna System Monitor (ASM) series products.

The version 2.50 firmware update file ("FFP") is available for download from the RFI website http://www.rfiwireless.com.au/multicoupling-monitoring/monitoring/antenna-system-monitor-asm3852.html#tab_downloads, and may be flashed into existing ASM models by following the *Maintenance – Firmware Update* process in the Graphical User Interface (GUI) or User Manual.

Product Enhancements

The version 2.50c firmware addresses the following product issues;

- i) The calculated VSWR value on the Channel Diagnostics page can differ from that displayed correctly on the Status pages in the GUI. This difference can vary based on the entered Tx Feeder Loss value.

Upgrading to Firmware 2.50c

Note: Please read all Service Bulletins published from the release of the firmware currently operating in your ASM prior to commencing an upgrade to this version 2.50b firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your ASM.

Firmware 2.50c *cannot* be applied to units currently operating firmware earlier than 2.0. Units must be updated to firmware 2.0 or 2.05 prior to attempting an update to 2.50.

Cost Impact

Firmware version 2.50c is available to RFI customers at no charge.

- END -